

TEMPORARY REVISION TR-MÄM DAIC-0042 AMEREX 337TS FIRE EXTINGUISHER

This temporary revision, TR-MÄM DAIC-0042, is approved in conjunction with Mandatory Design Change Advisory MÄM DAIC-0042, and is valid in conjunction with the latest revision of the DA 40 NG Airplane Flight Manual (AFM), until this temporary revision has been incorporated into the AFM.

The limitations and information contained herein either supplement, or in the case of conflict, override those in the AFM.

The technical information contained in this document has been approved by the Canadian Department of Transport.

Doc. No.	Chapter	Affected Pages			
6.01.15-E	4A	4A-5			
	6	6-19			

Instructions:

- Print this document on 8.5" x 11" yellow paper (single sided).
- Copy on yellow paper (single sided) at a reduced size of 72% to get the correct size for the AFM.
- Cut the paper to 6" x 8.5" and punch the holes on the left side of each page.
- Insert the cover page as the first page of the AFM.
- Insert the pages of this temporary revision in front of the corresponding pages in the AFM.
- Keep this temporary revision until the information has been incorporated into the DA 40 NG AFM.



4A.5 CHECKLISTS FOR NORMAL OPERATING PROCEDURES

4A.5.1 PRE-FLIGHT INSPECTION

I. Cabin Check

The following is added to the existing checklist:

v) Fire extinguisher charged and secure



6.5 EQUIPMENT LIST AND EQUIPMENT INVENTORY

The following is added to the existing table:

Airplane Serial No.:		Registration:		Date:		Mass		Lever Arm	
Description	Туре	Part No.	Manufacturer	S/N	Installed	lb	kg	in	m
SAFETY EQUIPMENT									
Fire extinguisher, portable		337TS	Amerex			3.17	1.44	110.0	2.794