

TEMPORARY REVISION

TR-OÄM-40-258

HID - Lights

This Temporary Revision TR-OÄM-40-258 is approved in conjunction with the Optional Design Change Advisory OÄM 40-258/a and is valid in conjunction with the latest revision of the DA 40 and DA 40F Airplane Flight Manual until this Temporary Revision has been incorporated into the Airplane Flight Manual.

The limitations and information contained herein either supplement or, in the case of conflict, override those in the Airplane Flight Manual.

The technical information contained in this document has been approved under the authority of DOA no. EASA.21J.052.

Affected Pages:

Doc. No.	Rev.	Page
6.01.01-E	7	6-18c
6.01.02-E	1	6-17b

Instruction:

- Print this document on yellow paper (single sided).
- Insert this cover page as the first page of the AFM.
- Insert the other pages of this Temporary Revision in front of the corresponding AFM pages.

Doc. No. 6.01.01-E Doc. No. 6.01.02-E	TR-OÄM 40-258	27-Nov-2007	Cover Page
--	---------------	-------------	------------

6.5 EQUIPMENT LIST AND EQUIPMENT INVENTORY

The following items are added to the Equipment List:

Airplane Serial No.:		Registration:		Date:	
Description	Type	Part No.	Manufacturer	S/N	in- stalled
LIGHTS					
% Ballast	GENS D1,24V	37776	NEWARK		
% Ballast	GENS D1,24V	37776	NEWARK		
% Taxi Light	HID LAMP D15	39663	NEWARK		
% Landing Light	HID LAMP D15	39663	NEWARK		