

SERVICE INFORMATION

No. SI 42-118

No. SI 40-112

No. SI D4-127

NOTE: SI's are used only:

- 1) To distribute information from DAI to our customers.
 - 2) To distribute applicable information/documents from our suppliers to our customers with additional information.
- Typically there is no revision service for SI's. Each new information or change of that will be sent along with a new SI.

I. TECHNICAL DETAILS

1.1 Airplanes affected:

All DA 42, DA 42 M, DA 40, DA 40 F and DA 40 D aircraft

1.2 Subject:

Illustrated Parts Catalogue (IPC) – Change of the available media

1.3 Reason:

In the future only the interactive version of the IPC will be available.

1.4 Information:

Diamond Aircraft announces that with immediate effect the following print/pdf versions of the Illustrated Parts Catalogue are withdrawn:

- Doc.No. 7.03.01, revision 4, dated 2008-11-10 (DA 42, DA 42 M)
- Doc.No. 6.03.01, revision 4, dated 2008-11-10 (DA 40)
- Doc.No. 6.03.02, revision 3, dated 2008-11-10 (DA 40 F)
- Doc.No. 6.03.05, revision 3, dated 2008-11-10 (DA 40 D)

In the future only the interactive IPC version of these documents will be available.
(public via the website <http://ipc.diamond-air.at/ipp4/> or on CR-ROM for Diamond Service Centers)



Diamond Aircraft Industries GmbH
N.A. Otto-Straße 5
A-2700 Wiener Neustadt
Austria

DAI SI 42-118
DAI SI 40-112
DAI SI D4-127
Page 2 of 2
5-Oct-2009
FT

II. OTHERS

In case of doubt contact Diamond Aircraft Industries GmbH.