Temporary Revision
Artex ELT 1000

TEMPORARY REVISION TR-OÄM-42-398 Artex ELT 1000

This Temporary Revision TR-OÄM-42-398 is approved in conjunction with the Optional Design Change Advisory OÄM 42-398 and is valid in conjunction with the latest revision of the DA 42 NG Airplane Flight Manual until this Temporary Revision has been incorporated into the Airplane Flight Manual.

The limitations and information contained herein either supplement or, in the case of conflict, override those in the Airplane Flight Manual or its previous Temporary Revisions.

The technical information contained in this document has been approved under the authority of DOA No. EASA.21J.052.

Doc. No.	Chapter	Affected Pages
7.01.15-E	6	6-21b

Instruction

- Print this document on yellow paper (single-sided).
- -Insert this cover page as the first page of the AFM.
- -Insert the other pages of this TR in front of the corresponding AFM pages.

Doc. No. 7.01.15-E TR-OÄM-42-398	20-Dec-2023	Cover Page
----------------------------------	-------------	------------



6.5 EQUIPMENT LIST AND EQUIPMENT INVENTORY

The follwing items are added to the equipment list:

Airplane Serial No.:		Registration:		Date:		Mass		Lever Arm	
Description	Type	Part No.	Manufacturer	S/N	installed	lb	kg	in	m
ELT unit	ELT 1000	A3-06-2749-1	Artex			1.950	0.885	179.700	4.565
ELT remote switch		345-6196	Artex						

Doc. No. 7.01.15-E TR-OÄM-42-398 20-Dec-2023 Page 6-21b