

TEMPORARY REVISION

AMM-TR-MÄM 42-1178

Improvement of Instrument Panel

This Temporary Revision AMM-TR-MÄM 42-1178 is approved in conjunction with the Mandatory Design Change Advisory MÄM 42-1178 and is valid in conjunction with the Airplane Maintenance Manual (AMM) until this Temporary Revision has been incorporated into the AMM.

The limitations and information contained herein either supplement or, in the case of conflict, override those in the AMM.

The technical information contained in this document has been approved under the authority of DOA No. EASA.21J.052.

Doc. No.	Section	Affected Pages
7.02.15	11-30-00	2a, 2aa

Instruction

- Print this document on yellow paper (double-sided).
- Insert this cover page as the first page of the AMM.
- Insert the other pages of this Temporary Revision adjacent to or in front of the corresponding AMM pages.

Intentionally left blank

CHAPTER 11
PLACARDS AND MARKINGS

Section 11-30
Interior Placards and Markings

2. Description

Figure 1 is amended to read:




Figure 1: Interior Placards and Markings

Intentionally left blank