

OPTIONAL SERVICE BULLETIN

OSB 42NG-075

I TECHNICAL DETAILS

I.1 Category

Optional.

I.2 Airplanes affected

Type: DA 42 NG /M-NG
Serial numbers: 42.N233 and subsequent
42.MN055 and subsequent
with Garmin GTX 335R transponder installed (MÄM 42-978)

I.3 Date of effectivity

05-Apr-2018

I.4 Time of Compliance

At owner's discretion

I.5 Subject

Activation of ADS-B Out functionality.
ATA-Code: 34-50

I.6 Reason

This Service Bulletin provides instructions for the activation of ADS-B Out functionality of the Garmin GTX 335R transponder.

I.7 Concurrent Documents

None.

I.8 Approval

The technical information or instructions contained in this document relate to the Design Change Advisory No. OÄM 42-258, which has been approved under the authority of EASA Design Organization Approval ref. EASA.21J.052.

The technical content of this document has been approved under the authority of DOA ref. EASA.21J.052.

I.9 Accomplishments / Instructions

Comply with WI-OSB 42NG-075, latest effective issue.

I.10 Mass (Weight) and CG

Not affected.

II PLANNING INFORMATION**II.1 Material and Availability**

See WI-OSB 42NG-075, latest effective issue.

Materials including drawings are available from Diamond Aircraft Industries.

II.2 Special Tools

None.

II.3 Labour Effort

Approx. 2 hours.

II.4 Credit

None.

II.5 Reference Documents

DA 42 NG Airplane Maintenance Manual, Doc. No. 7.02.15, latest effective issue.

III REMARKS

1. All work must be done by a certified aircraft service station or a certified aircraft maintenance mechanic.
2. All work, particular that which is not especially described in this Service Bulletin, must be done in accordance with the referenced Maintenance Manual.
3. Completion of all work must be recorded in the log book.
4. In case of doubt contact Diamond Aircraft Industries GmbH.

EXECUTION REPORT TO SERVICE BULLETIN OSB 42NG-075

AIRPLANE INFORMATION

Airplane Serial Number _____

Airplane Registration _____

Airplane Operator _____

Hours of operation of airplane _____

No. of landings _____

Hours of operation-engine LH _____

RH _____

Typical operation of airplane private, club, training, other _____

Date, Name, Sign

Please fax the completed form to Fax No. +43-2622-26780
or e-mail to executionreports@diamond-air.at