DA 42 AFM with OÄM 42-102 Garmin GFC 700



TEMPORARY REVISION TR-MÄM-42-1265 New Fire Extinguisher

This Temporary Revision TR-MÄM-42-1265 is approved in conjunction with the Mandatory Design Change Advisory MÄM 42-1265 and is valid in conjunction with the latest revision of the DA 42 Airplane Flight Manual until this Temporary Revision has been incorporated into the Airplane Flight Manual.

The limitations and information contained herein either supplement or, in the case of conflict, override those in the Airplane Flight Manual or its previous Temporary Revisions.

The technical information contained in this document has been approved under the authority of DOA No. EASA.21J.052.

Doc. No.	Chapter	Affected Pages
7.01.06-E	3	3-44a
	4	4A-7a
	6	6-19a

Instruction

- -Print this document on yellow paper (single-sided).
- -Insert this cover page as the first page of the AFM.
- -Insert the other pages of this TR in front of the corresponding AFM pages.

Doc. # 7.01.06-E	TR-MÄM-42-1265	13-Mar-2023	Cover Page
------------------	----------------	-------------	------------



3.11 SMOKE AND FIRE

The second note is amended to read:

NOTE

The fire extinguisher is located on the cabin floor behind the co-pilot's seat.

If AIR TOTAL HAL 1 is installed: To release the fire extinguisher out of the fire extinguisher mount, pull the fire extinguisher at the nozzle near the Y-spring.

If Amerex A620T (OÄM 42-127) or Amerex 337TS (MÄM 42-1265) is installed: To release the fire extinguisher out of the fire extinguisher mount, open the holding strap and pull the fire extinguisher out.

Doc. # 7.01.06-E	TR-MÄM-42-1265	13-Mar-2023	Page 3-44a
------------------	----------------	-------------	------------



4A.6 CHECKLISTS FOR NORMAL OPERATING PROCEDURES

4A.6.1 PRE-FLIGHT INSPECTION

I. Cabin Check

Preparation:

The following item is added:

i)	Fire extinguisher (if installed)	stowed and secured
		pressure in green arc
	if AIR TOTAL HAL 1 is installed	no damage of the tamper seal

Doc. # 7.01.06-E	TR-MÄM-42-1265	13-Mar-2023	Page 4A-7a
------------------	----------------	-------------	------------

DA 42 AFM with OÄM 42-102 Garmin GFC 700



6.5 EQUIPMENT LIST AND EQUIPMENT INVENTORY

The following item is amended to read:

Airplane Serial No.:		Registration:		Date:		Ma	SS	Lever	Arm
Description	Туре	Part No.	Manufacturer	S/N	installed	lb	kg	in	m
Fire extinguisher		AIR TOTAL HAL 1	TOTAL Feuerschutz						

The follwing item is added to the Equipment list:

Airplane Serial No.:		Registration:		Date:		Ma	SS	Lever	Arm
Description	Туре	Part No.	Manufacturer	S/N	installed	lb	kg	in	m
Fire extinguisher		337TS	Amerex						

Doc. # 7.01.06-E	TR-MÄM-42-1265	13-Mar-2023	Page 6-19a
------------------	----------------	-------------	------------