

Diamond Aircraft Industries GmbH N. A. Otto-Straße 5 2700 Wiener Neustadt Austria

DAI OSB 42-119 DAI OSB 42NG-053/1 Page 1 of 3 29-Feb-2016

OPTIONAL SERVICE BULLETIN OSB 42-119 OSB 42NG-053/1

SUPERSEDES MSB 42NG-053

I <u>TECHNICAL DETAILS</u>

I.1 Category

Optional.

I.2 Airplanes affected

Type: DA 42, DA 42, DA 42 NG, DA 42 M-NG

Serial numbers: 42.004 and subsequent

42.AC001 and subsequent 42.M001 and subsequent 42.N001 and subsequent 42.MN001 and subsequent

I.3 Date of effectivity

09-Apr-2015

I.4 <u>Time of Compliance</u>

At owner's discretion

I.5 Subject

Installation of a GPS-Tracker as Carry-On Equipment.

I.6 Reason

For tracking of the airplanes position a GPS Tracker can be installed as Carry-On Equipment. This Service Bulletin describes the installation of the provisions.

I.7 Concurrent Documents

None.

I.8 Approval

The technical information or instructions contained in this document relate to the Design Change Advisory No. OÄM 42-282/a, which has been approved under the authority of EASA Design Organization Approval ref. EASA.21J.052.



Diamond Aircraft Industries GmbH N. A. Otto-Straße 5 2700 Wiener Neustadt Austria

DAI OSB 42-119 DAI OSB 42NG-053/1 Page 2 of 3 29-Feb-2016

The technical content of this document has been approved under the authority of DOA ref. EASA.21J.052.

I.9 Accomplishments / Instructions

Comply with WI-OSB 42-119/WI-OSB 42NG-053, latest effective issue.

I.10 Mass (Weight) and CG

The change in mass and CG is negligible.

II PLANNING INFORMATION

II.1 Material and Availability

See WI-OSB 42-119/WI-OSB 42NG-053, latest effective issue.

II.2 Special Tools

None.

II.3 Labour Effort

Approx. 2 hours.

II.4 Credit

None.

II.5 Reference Documents

DA 42 Series Airplane Maintenance Manual, Doc. No. 7.02.01, latest effective issue.

DA 42 NG Airplane Maintenance Manual, Doc. No. 7.02.15, latest effective issue.

III REMARKS

- 1. All work must be done by a certified aircraft service station or a certified aircraft maintenance mechanic.
- 2. All work, in particular that which is not especially described in this Service Bulletin, must be done in accordance with the referenced Maintenance Manual.
- 3. Completion of all work must be recorded in the log book.
- 4. In case of doubt contact Diamond Aircraft Industries GmbH.



Diamond Aircraft Industries GmbH N. A. Otto-Straße 5 2700 Wiener Neustadt Austria

DAI OSB 42-119 DAI OSB 42NG-053/1 Page 3 of 3 29-Feb-2016

EXECUTION REPORT TO SERVICE BULLETIN OSB 42-119 OSB 42NG-053/1

AIRPLANE INFORMATION			
Airplane Serial Number			-
Airplane Registration			-
Airplane Operator			-
Hours of operation of airplane			-
No. of landings			-
Hours of operation-engine	LH		-
	RH		-
Typical operation of airplane	private,	, club, training, other	
Date, Name, Sign			

Please fax the completed form to Fax No. +43-2622-26700-1369 or e-mail to airworthiness@diamond-air.at