

9.05.01
Chapter 1

DA 50 C



LIST OF APPLICABLE DIAMOND PUBLICATIONS · last update: 2025-08-28

Doc. No.	Description	Initial Issue	Issue/Rev.	Ser.Nos. affected (SB/SI)	Remarks	PDF available
9.01.01-E	AIRPLANE FLIGHT MANUAL (english) - BASIC MANUAL Airplane Flight Manual (AFM)		20	2025-08-07	Complete Manual	NEW X
9.01.01-E	AIRPLANE FLIGHT MANUAL (english) - SUPPLEMENTS Supplement A034, Electronic Stability and Protection System (ESP)	2021-06-23	2	2025-08-07		NEW X
	Supplement N022, Operation in China	2021-11-10	2	2025-08-07		NEW X
	Supplement N023, Operation in Brazil	2025-01-09	2	2025-08-07		NEW X
	Supplement O008, Removable RH Control Stick	2021-03-10	2	2025-08-07		NEW X
	Supplement O015, Business Seating Configuration Passenger Seat Row	2022-11-03	2	2025-08-07		NEW X
	Supplement S003, Ice Protection System for Flight Into Known Icing	2022-06-03	3	2025-08-07		NEW X
	Supplement S004, Continuous Flow Oxygen System		3	2025-08-07		NEW X
	Supplement S007, Air Conditioning System	2022-05-13	3	2025-08-07		NEW X
	Supplement S013, Flight Stream 510	2020-12-03	2	2025-08-07		NEW X
9.01.01-E	AIRPLANE FLIGHT MANUAL (english) - VALID TEMPORARY REVISIONS TR-OÄM-50-066, Beringer Tyre Pressure and Temperature Monitoring System	2025-08-11				NEW X
9.02.01	AIRPLANE MAINTENANCE MANUAL (english) - BASIC MANUAL Airplane Maintenance Manual (AMM)		14	2025-02-12	Complete Manual	X
9.03.01	ILLUSTRATED PARTS CATALOGUE (english) - BASIC MANUAL Illustrated Parts Catalogue (IPC)	2022-12-14	current (N/A)		online available	X

LIST OF APPLICABLE DIAMOND PUBLICATIONS · last update: 2025-08-28

Doc. No.	Description	Initial Issue	Issue/Rev.	Ser.Nos. affected (SB/SI)	Remarks	PDF available
SERVICE BULLETIN LIST						
SB50-001	not issued yet					-
MSB50-002/4	Software for Continental Aerospace Technologies GmbH Centurion 3.0 (CD-300) Engine, approved versions	2021-05-26	4	2024-09-05	DA 50 C S/N 50.002, 50.003, 50.006, 50.C.A.A.007 and subsequent, 50.C.Q.A.001 and subsequent	X
MSB50-003/7	Software for Garmin G1000 NXi; approved software systems, manifests and configurations	2021-05-12	7	2025-04-30	DA 50 C S/N 50.002, 50.003, 50.006, 50.C.A.A.007 and subsequent, 50.C.Q.A.001 and subsequent	X
OSB50-004	Activation of Garmin Flight Stream 510	2022-05-30	-		DA 50 S/N 50.002, 50.003, 50.006, 50.C.A.A.007 and subsequent	X
OSB50-005	Installation of Halon-free Fire Extinguisher Amerex 337 TS	2023-08-23	-		DA 50 S/N 50.002, 50.003, 50.006, 50.C.A.A.007 to 50.C.A.A.042, 50.C.A.A.046, 50.C.A.A.048	X
OSB50-006/1	Optional retrofit installation of an oxygen system	2023-08-17	1	2023-09-19	DA 50 S/N 50.C.A.A.007 and subsequent	X
RSB50-007	Lubrication of flap actuator trigger rod	2024-06-27	-		DA 50 S/N 50.C.A.A.007 through 50.C.A.A.049, 50.C.A.A.052, 50.C.A.A.054, 50.C.A.A.056	X
MSB50-008	Retorquing the horizontal stabilizer bolts	2024-07-01	-		DA 50 S/N 50.C.A.A.007 through 50.C.A.A.049, 50.C.A.A.052, 50.C.A.A.054, 50.C.A.A.056	X
OSB50-009	Installation of plastic NLG bushings, NLG fork with reduced castor length and new shape NLG doors	2024-12-20	-		DA 50 S/N 50.C.A.A.007 through 50.C.A.A.066, 50.C.A.A.070 through 50.C.A.A.074, 50.C.Q.A.001 through 50.C.Q.A.003	X
SB50-010	not issued yet		-			-
OSB50-011	Installation of Control System Sealing Foams	2024-12-16	-		DA 50 S/N 50.C.A.A.007 through 50.C.A.A.081, 50.C.Q.A.001 through 50.C.Q.A.003	X
MSB50-012	Replacement of the Main Landing Gear Retaining Rings	2025-07-01	-		DA 50 S/N 50.C.A.A.007 through 50.C.A.A.068, 50.C.A.A.070 through 50.C.A.A.073, 50.C.Q.A.001 through 50.C.Q.A.002	X
SB50-013	not issued yet		-			-
OSB50-014	Installation of balance mass on NLG bulkhead	2025-06-27	-		DA 50 S/N 50.C.A.A.007 and subsequent, 50.C.C.A.001 and subsequent, 50.C.Q.A.001 and subsequent	X
SERVICE INFORMATION LIST						
SI50-001/2	Descriptions of DAI technical publication systems and handling of documents	2021-06-10	2	2023-12-05	DA 50 C, all serial numbers	X
SI50-002	Garmin SB No. 22117 Rev. B, Replacement of the cable retention pins at the GSM 86 servo gearbox assembly	2023-03-20	-		DA 50 C, all serial numbers	X
SI50-003	Continental Aerospace Technologies GmbH Priority 1 Safety SB CG 300-2023-09-29 1001 P1, Oil analysis of Centurion 3.0	2023-09-29	-		DA 50 C, all serial numbers	X
SI50-004	Continental Aerospace Technologies GmbH Priority 1 Safety SB CG 300-2023-10-10 1001 P1 Rev. 1, Oil analysis of Centurion 3.0	2023-10-10	-		DA 50 C, all serial numbers	X
SI50-005	Garmin Mandatory SB No. 24088 Rev. A, Removal and replacement of any affected GIA 64 unit	2025-01-13	-		DA 50 C, all serial numbers	X
SI50-006	Safe Flight Service Bulletin for Lift Transducer C-99707-2	2025-06-12	-		DA 50 C, all serial numbers	X