

OPTIONAL SERVICE BULLETIN

OSB 62-015

I TECHNICAL DETAILS

I.1 Category

Optional.

I.2 Airplanes affected

Type: DA 62
Serial numbers: 62.009 and subsequent

I.3 Date of effectivity

24-May-2017

I.4 Time of Compliance

At owner's discretion.

I.5 Subject

Installation of armrest with integrated keypad.

ATA-Code: 31-00

I.6 Reason

Diamond has developed an armrest with integrated Garmin GCU 476 keypad for ease of data entry.
This Service Bulletin describes the installation of an armrest with integrated Garmin GCU 476 keypad for aircrafts already in service.

I.7 Concurrent Documents

None.

I.8 Approval

The technical information or instructions contained in this document relate to the Design Change Advisory No. OÄM 62-031, which has been approved under the authority of EASA Design Organization Approval ref. EASA.21J.052.

The technical content of this document has been approved under the authority of DOA ref. EASA.21J.052.

I.9 Accomplishments / Instructions

See WI-OSB 62-015, latest effective issue.

I.10 Mass (Weight) and CG

Mass (Weight) and CG affected.

II PLANNING INFORMATION**II.1 Material and Availability**

See WI-OSB 62-015, latest effective issue.

II.2 Special Tools

See WI-OSB 62-015, latest effective issue.

II.3 Labour Effort

Approx. 100 hours.

II.4 Credit

None.

II.5 Reference Documents

DA 62 Airplane Maintenance Manual, Doc. No. 7.02.25, latest effective issue.

III REMARKS

1. All work must be done by a certified aircraft service station or a certified aircraft maintenance mechanic.
2. All work, in particular that which is not especially described in this Service Bulletin, must be done in accordance with the referenced Maintenance Manual.
3. Completion of all work must be recorded in the log book.
4. In case of doubt contact Diamond Aircraft Industries GmbH.

EXECUTION REPORT TO SERVICE BULLETIN OSB 62-015

AIRPLANE INFORMATION

Airplane Serial Number _____

Airplane Registration _____

Airplane Operator _____

Hours of operation of airplane _____

No. of landings _____

Hours of operation-engine LH _____

RH _____

Typical operation of airplane private, club, training, other _____

Date, Name, Sign

Please fax the completed form to Fax No. +43-2622-26700-1369 or e-mail to
executionreports@diamond-air.at