

TEMPORARY REVISION

TR-MÄM-20-475

New Fire Extinguisher

This Temporary Revision TR-MÄM-20-475 is approved in conjunction with the Mandatory Design Change Advisory MÄM 20-475 and is valid in conjunction with the latest revision of the DV 20 Airplane Flight Manual until this Temporary Revision has been incorporated into the Airplane Flight Manual.

The limitations and information contained herein either supplement or, in the case of conflict, override those in the Airplane Flight Manual or its previous Temporary Revisions.

The technical information contained in this document has been approved under the authority of DOA No. EASA.21J.052.

Doc. No.	Chapter	Affected Pages
4.01.20-E	3	3-9a
	4	4-5a
	6	6-18a

Instruction

- Print this document on yellow paper (single-sided).
- Insert this cover page as the first page of the AFM.
- Insert the other pages of this TR in front of the corresponding AFM pages.

Doc. No. 4.01.20-E	TR-MÄM-20-475	09-Aug-2023	Cover Page
--------------------	---------------	-------------	------------

CHAPTER 3 - EMERGENCY PROCEDURES

3.3 EMERGENCY PROCEDURES - CHECKLISTS

3.3.3 Fire

The following note is added:

NOTE

The fire extinguisher is located in the baggage compartment behind the co-pilot's seat.

To release the fire extinguisher out of the fire extinguisher mount, open the holding strap and pull the fire extinguisher out.

CHAPTER 6 - MASS (WEIGHT) AND BALANCE / EQUIPMENT LIST

6.5 EQUIPMENT LIST

The following item is added to the equipment list:

Equipment List		Airplane Serial No.:		Registr.:	
				Date:	
Seq. No.:	Part Description, Manufacturer, Type	Serial No.:	Inst.	Mass [kg] (lbs)	Arm [m] (in)
Z 18	Fire Extinguisher AMEREX 337TS				+ 0.660 (+ 25.98)