

**TEMPORARY REVISION**  
**TR-OÄM-36-352**  
**Supplement 1, Revision 4**

This Temporary Revision TR-OÄM-36-352 is approved in conjunction with the Optional Design Change Advisory OÄM 36-352 and is valid in conjunction with the latest revision of the HK 36 TC-100 Airplane Flight Manual until this temporary revision has been incorporated into the Airplane Flight Manual.

The limitations and information contained herein either supplement or, in the case of conflict, override those in the Airplane Flight Manual.

The technical information contained in this document has been approved under the authority of DOA No. EASA.21J.052.

**9.2 LIST OF SUPPLEMENTS**

**THE ENTRY IN THE EXISTING TABLE IS AMENDED TO READ:**

| Airplane S/N.: |                     | Call Sign: |            | Date:                    |                          |
|----------------|---------------------|------------|------------|--------------------------|--------------------------|
| Suppl. No.     | Title               | Rev. No.   | Date       | applicable               |                          |
|                |                     |            |            | YES                      | NO                       |
| 1              | Tow-Plane Operation | 4          | 24-10-2011 | <input type="checkbox"/> | <input type="checkbox"/> |