



DA42 Series (Austro Engine) to DA40 (Austro Engine)

Difference Type Training (theoretical and practical course)

calendarweek 44 (Tuesday, 27.October 2020)

Fee for the theory and practice course (per person): **Euro 930,--** (excl. VAT / € 1.116,- incl. 20% VAT)

Bank transfer deadline: 28.September 2020

The **DA42 to DA40 (Austro Engine)** Difference Type Training course is in compliance with

EASA - (EU No 1321/2014 Part66/Appendix III - Type Training B1.2, C - Piston Engine

The training contains the differences between the Diamond DA42 Series (Austro Engine) to the Diamond DA40 (Austro Engine) and is created for technicians, who have already the DA42 (Austro Engine) endorsement in their Aircraft Maintenance Licence.

If the DA42 (Austro Engine) isn't in your maintenance licence, the full Type Training course for the relevant type (DA40 (Austro Engine)) is necessary!

For licensing, Diamond recommends that you always get in contact with your National Authority!

Course duration: 6 hours (1 day)
09.00 a.m. - 04.00 p.m.

Course level: Line and Base Maintenance B1.2 / Level 3

Course start: 09.00 a.m. local time

Participants: minimum 4, maximum 10 persons

Note: We reserve the right to cancel a course if there are not enough participants. In this case we will propose an alternative date.

Place: Diamond Maintenance Training
Ferdinand Graf v. Zeppelinstr. 5/1.floor
A-2700 Wr. Neustadt/AUSTRIA

Please Notice!

According to the Austro Engine Maintenance Manual all inspections and repairs on the AE300 engine have to be carried out by an organisation which is authorised by Austro Engine.

This course is created together with  **Austro Engine** and covers this requirements for AE Service Center.