

Model DA 40 NG

MANDATORY SERVICE BULLETIN NO. MSB 40NG-059 REV. 1 SUPERSEDES MSB 40NG-059 REV. 0

1. TECHNICAL DETAILS

1.1 Category

Mandatory

1.2 Airplanes Affected

Type: DA 40 NG

Serial Numbers:	D4.393
	40.N139 through 40.N147
	40.N165 through 40.N181
	40.N257 through 40.N260
	40.N270 through 40.N340
	40.N367 through 40.N384
	40.N088, 40.N188, 40.N224, 40.N225, 40.N345, 40.N346 40.N364,
	40.N377, 40.N388

1.3 Date of Effectivity

16 May 2019

1.4 Time of Compliance

Implement at next maintenance action. Compliance with Revision 1 of this service bulletin is not required if Revision 0 has already been implemented.

1.5 Subject

I

DA 40 NLG Tire Pressure Placard

1.6 Reason

It has come to DAI's attention that a number of DA 40 NG aircraft that have MÄM-40-631 installed may be fitted with an incorrect tire pressure placard. Customers are advised to confirm the tire pressure placard located on the NLG is applicable to the aircraft type.

1.7 Concurrent Documents

DA 40 NG Aircraft Maintenance Manual, latest effective issue

Diamond Aircraft Industries **MANDATORY SERVICE BULLETIN**



Model DA 40 NG

1.8 Approval

The technical information or instructions contained in this document are approved as part of the type design.

1.9 Accomplishment/Instructions

Customers are advised to confirm that the correct tire pressure placard is installed on the nose landing gear. The pressure placard is dependent on the aircraft configuration as outlined in Table 1. For additional information, refer to the AMM Chapter 11-20-00.

NLG Configuration	Tire Pressure Placard	Part Number
Basic Configuration	3.1 bar / 45 psi	D44-1123-10-23
OÄM 40-334	1.2 bar / 17 psi	D44-1123-10-23X01
MÄM 40-631	2.4 bar / 35 psi	D44-1123-10-25

Table 1: NLG Tire Placard List

Upon inspection, if an incorrect placard is found to be installed, remove it, and replace it with correct placard. Verify tire pressure, and adjust as necessary.

1.10 Mass (Weight) and CG

Not applicable

2. PLANNING INFORMATION

2.1 Material and Availability

Air Pressure LG Placard - D44-1123-10-23	(As required)
Air Pressure LG Placard - D44-1123-10-23X01	(As required)
Air Pressure LG Placard - D44-1123-10-25	(As required)

2.2 Special Tools

Not applicable

2.3 Labour Effort

For Inspection:	not applicable
For Replacement:	approximately 15 minutes

2.4 Credit

Not applicable



Model DA 40 NG

2.5 Reference Documents

DA 40 NG Airplane Maintenance Manual, Doc. No. 6.02.15, latest effective issue

3. <u>REMARKS</u>

- 1. All work must be completed by the appropriate authorized personnel.
- 2. All work, particular that, which is not especially described in this service bulletin, must be done in accordance with the referenced maintenance manual.
- 3. Completion of all work must be recorded in the logbook.
- 4. In case of doubt, contact Diamond Aircraft Industries.

To obtain satisfactory results, procedures specified in this service bulletin must be accomplished in accordance with accepted methods and current government regulations. Diamond Aircraft cannot be responsible for the quality of work performed in accomplishing the requirements of this service bulletin. Diamond Aircraft reserves the right to void continued warranty coverage in the area affected by this service bulletin if it is not incorporated.

If you no longer own the aircraft to which this service bulletin applies, please forward it to the current owner and send the name of the current owner to Diamond Aircraft at the address below.

Diamond Aircraft Industries GmbH N. A. Otto-Straße 5, 2700 Wiener Neustadt, Austria Diamond Aircraft Industries Inc. 1560 Crumlin Sideroad, London, Ontario, Canada N5V 1S2

Customer Support: Phone: (519) 457-4041 Fax: (519) 457-4045 E-mail: custsupp@diamondair.com Technical Publications: E-mail: techpubs@diamondair.com



EXECUTION REPORT TO SERVICE BULLETIN MSB 40NG-059 REV. 1

AIRPLANE DATA

Airplane Serial Number					
Airplane Registration					
Airplane Operator					
Hours of Operation Airplane (TSN)					
Typical operation of airplane	private, club, training, other:				
MAINTENANCE DATA:					
Inspection carried out on					
Inspection carried out by					
During scheduled inspection:	Yes No				
NLG Configuration	Basic 🔲 MÄM-40-631 🔲 OÄM-40-334 🗌				
Current Installed Placard P/N					
Replaced with P/N					
Date					
	Qiana at una				
Name	Signature				

Please e-mail the completed form to techpubs@diamondair.com